


FACILITY CONDITION ASSESSMENT

Dobie MS | February 2022





Executive Summary

Dobie MS is located at 1200 E Rundberg Ln in Austin, Texas. The oldest building is 47 years old (at time of 2020 assessment). It comprises 138,751 gross square feet.

The findings contained within this report are the result of an assessment of building systems and the conditions found on the site at the time of the visit. The assessment was performed by building professionals experienced in disciplines including architecture, mechanical, plumbing and electrical. The total current deficiencies for this site, in 2020 construction cost dollars, are estimated at \$15,739,682. A ten-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Dobie MS the ten-year need is \$22,564,970.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined to calculate a Facility Condition Assessment (FCA) score. A 5-year FCA was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCA calculation. The Dobie MS facility has a 5-year FCA score of 53.45%.

Summary of Findings

The table below summarizes the condition findings at Dobie MS

Table 1: Facility Condition by Building

Number	Building Name	Current Deficiencies	5-Year Life Cycle Cost	Yrs 6-10 Life Cycle Cost	Total 5 Yr Need (Yr 1-5 + Current Defs)	Total 10 Yr Need (Yr 1-10 + Current Defs)	Replacement Cost	5-Year FCA
Exterior Si	te							
	Exterior Site	\$1,559,098	\$913,185	\$0	\$2,472,283	\$2,472,283	\$0	
Permanent	t Building(s)				•			
055A	Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.	\$13,698,265	\$4,050,151	\$1,304,442	\$17,748,416	\$19,052,858	\$42,095,330	57.84%
055B	Stand-Alone Classroom Building	\$482,320	\$509,366	\$48,144	\$991,686	\$1,039,830	\$3,469,112	71.41%
	Sub Total for Permanent Building(s):	\$14,180,584	\$4,559,517	\$1,352,586	\$18,740,101	\$20,092,687	\$45,564,444	
	Total for Site:	\$15,739,682	\$5,472,702	\$1,352,586	\$21,212,384	\$22,564,970	\$45,564,444	53.45%



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates the ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

All members of the survey team recorded existing conditions, identified problems and deficiencies, and documented corrective action and quantities. The team took digital photos at each site to better identify significant deficiencies.

Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – **Mission Critical Concerns:** Deficiencies or conditions that may directly affect the site's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the site's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following table summarizes this site's current deficiencies by building system and priority.

Table 2: System by Priority (Site & Permanent Buildings)

			Priority				
System	1	2	3	4	5	Total	% of Total
Site	\$0	\$0	\$0	\$25,854	\$1,520,335	\$1,546,188	9.83 %
Roofing	\$2,265,737	\$0	\$0	\$0	\$0	\$2,265,737	14.41 %
Structural	\$12,910	\$0	\$0	\$0	\$0	\$12,910	0.08 %
Exterior	\$0	\$10,399	\$1,149	\$0	\$0	\$11,548	0.07 %
Interior	\$0	\$0	\$263,894	\$635,939	\$74,101	\$973,934	6.19 %
Mechanical	\$0	\$2,309,288	\$67,248	\$215,181	\$0	\$2,591,716	16.48 %
Electrical	\$0	\$384,932	\$2,644,796	\$0	\$0	\$3,029,728	19.27 %
Plumbing	\$0	\$7,306	\$882,800	\$286,419	\$0	\$1,176,524	7.48 %
Fire and Life Safety	\$615,838	\$0	\$0	\$0	\$0	\$615,838	3.92 %
Conveyances	\$0	\$98,739	\$0	\$0	\$0	\$98,739	0.63 %
Specialties	\$0	\$0	\$0	\$375,053	\$0	\$375,053	2.39 %
Crawlspace	\$0	\$0	\$0	\$0	\$3,027,152	\$3,027,152	19.25 %
Total:	\$2,894,485	\$2,810,663	\$3,859,887	\$1,538,446	\$4,621,587	\$15,725,068	

The building systems at the site with the most need include:

Electrical	-	\$3,029,728
Mechanical	-	\$2,591,716
Roofing	-	\$2,265,737



The chart below represents the building systems and associated deficiency costs.




Figure 1: System Deficiencies



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If an assessor identified a need for immediate replacement, a deficiency was created with the item's repair costs. The identified deficiency contributes to the facility's total current repair costs.

However, capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a ten-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following tables show current deficiencies and the subsequent ten-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3a: Capital Renewal Forecast (Yrs 1-5)

		Life Cycl	e Capital Renewal Pr	ojections		
System	Year 1 2023	Year 2 2024	Year 3 2025	Year 4 2026	Year 5 2027	Total 1-5
Site	\$0	\$0	\$0	\$140,728	\$1,018,014	\$1,158,742
Roofing	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$0	\$0	\$0	\$0	\$290,168	\$290,168
Interior	\$0	\$531,919	\$168,801	\$0	\$1,823,275	\$2,523,995
Mechanical	\$0	\$0	\$0	\$0	\$16,072	\$16,072
Electrical	\$0	\$0	\$0	\$0	\$334,805	\$334,805
Plumbing	\$0	\$0	\$0	\$0	\$17,951	\$17,951
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0
Conveyances	\$0	\$0	\$0	\$0	\$23,954	\$23,954
Specialties	\$70,415	\$352,075	\$0	\$0	\$964,543	\$1,387,033
Crawlspace	\$0	\$0	\$0	\$0	\$0	\$0
Total	\$70,415	\$883,994	\$168,801	\$140,728	\$4,488,782	\$5,752,720



Table 3b: Capital Renewal Forecast (Yrs 6-10)

			Life Cycle	Capital Renewal F	Projections			
System	Total 1-5	Year 6 2028	Year 7 2029	Year 8 2030	Year 9 2031	Year 10 2032	Total 6-10	Total 1-10
Site	\$1,158,742	\$0	\$0	\$0	\$0	\$0	\$0	\$1,158,742
Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$290,168	\$0	\$0	\$0	\$0	\$67,473	\$67,473	\$357,641
Interior	\$2,523,995	\$0	\$0	\$0	\$481,507	\$7,242	\$488,749	\$3,012,744
Mechanical	\$16,072	\$0	\$0	\$0	\$0	\$1,002,037	\$1,002,037	\$1,018,109
Electrical	\$334,805	\$0	\$0	\$0	\$0	\$0	\$0	\$334,805
Plumbing	\$17,951	\$0	\$0	\$0	\$3,173	\$24,345	\$27,518	\$45,469
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Conveyances	\$23,954	\$0	\$0	\$0	\$0	\$0	\$0	\$23,954
Specialties	\$1,387,033	\$0	\$0	\$0	\$0	\$0	\$0	\$1,387,033
Crawlspace	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Total	\$5,752,720	\$0	\$0	\$0	\$484,680	\$1,101,097	\$1,585,777	\$7,338,497




Figure 2: Ten Year Capital Renewal Forecast



Facility Condition Assessment Score

The Facility Condition Assessment Score (FCAS) is used throughout the facility condition assessment industry as a general indicator of a building's health. The FCAS is used to benchmark the relative condition of a group of sites. The FCAS is derived by dividing the total repair cost, site-related repairs, by the total replacement cost and subtracting it from 100. A facility with a lower FCAS percentage has more need, or higher priority, than a facility with a lower FCAS. It should be noted that costs in the New Construction category are not included in the FCAS calculation.


FCAS = 100 - (Total Repair Cost/ Replacement Cost)

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCAS was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCAS calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair sites with a FCAS of 35 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCAS at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCAS is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making campus facility decisions.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Austin area. The estimated replacement cost for this facility is \$45,564,444. For planning purposes, the total 5-year need at the Dobie MS is \$21,212,384 (Life Cycle Years 1-5 plus the FCA deficiency cost). The Dobie MS facility has a 5-year FCA of 53.45%.



M-A-P-P-S ©, Jacobs 2022



Dobie MS - Deficiency Summary Site Level Deficiencies

Site

Deficiency	Category	Qty UoN	Priority	Repair Cost	ID
Fencing Replacement (8' - 10' high Chain Link Fence)	Capital Renewal	330 LF	4	\$25,854	4851
Note: Rusted, age					
Location: Northwest side along Teasdale Avenue					
Paving Restriping	Deferred Maintenance	97 CAR	5	\$3,226	4855
Location: Asphalt parking lots					
PROGRAM DEFICIENCIES	ADA Compliance	482,089 EAC	H 5	\$827,738	5475
PUBLIC DEFICIENCIES	ADA Compliance	310,541 EAC	H 5	\$533,193	5472
TAS ACCESSIBILITY DEFICIENCIES	ADA Compliance	90,961 EAC	H 5	\$156,178	5476
	Sub Total for System	5 item	s	\$1,546,188	
Structural					
Deficiency	Category	Qty UoN	Priority	Repair Cost	ID
Structural Study Recommended	Deferred Maintenance	2 Job	1	\$12,910	6679

Note: Structural study to detail scope of work based on the 2017 crawlspace deficiencies provided by AISD

Sub Total for System 1 items \$12,910


Sub Total for School and Site Level 6 items \$1,559,098

Building: 055A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.

Roofing

J						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
AISD ROOFING P1	Capital Renewal	22,586	EACH	1	\$23,754	5478
AISD ROOFING P2	Capital Renewal	346,148	EACH	1	\$364,044	5479
AISD ROOFING P3	Capital Renewal	1,397,068	EACH	1	\$1,469,298	5480
AISD ROOFING P4	Capital Renewal	317,938	EACH	1	\$334,376	5481
AISD ROOFING P5	Capital Renewal	70,615	EACH	1	\$74,266	5482
	Sub Total for System	5	items		\$2,265,737	
Exterior						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Stucco Exterior Wall Replacement (Bldg SF)	Capital Renewal	2,000	SF	2	\$10,399	5254
Note: age, weathered						
Location: north wall						
Exterior Metal Door Repainting	Deferred Maintenance	10	Door	3	\$1,149	5255
	Sub Total for System	2	items		\$11,548	
Interior						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Interior Door Hardware Replacement	Capital Renewal	67	Door	3	\$99,469	5177
Note: to be replaced with replacement doors						
Interior Door Replacement	Capital Renewal	67	Door	3	\$125,665	5175
Note: end of life						
Location: various locations						
Rubber Flooring Replacement	Capital Renewal	2,564	SF	3	\$38,760	5172
Note: end of life						
Location: stairway treads						
Acoustical Ceiling Tile Replacement	Capital Renewal	32,047	SF	4	\$108,215	5169
Note: damaged						
Location: various locations						








Interior

Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Toilet Partition Replacement	Capital Renewal	16 Stall	4	\$32,264	5171
Note: end of life					
Location: various restrooms					
Vinyl Composition Tile Replacement	Capital Renewal	38,456 SF	4	\$314,482	5173
Note: end of life					
Location: various locations					
Wood Flooring Repair	Deferred	4,800 SF	4	\$79,503	5174
	Maintenance				
Note: buckling and refinishing					
Location: small gym and stage, respectively			_		
Interior Door Repair	Deferred Maintenance	20 Door	5	\$12,910	5176
Note: inoperable					
Location: various locations					
Interior Gypsum Board Wall Repainting	Deferred	30,000 SF	5	\$38,729	5170
71	Maintenance	Wall			
Note: scuffs, stains, flaking					
Location: various locations					
	Sub Total for System	9 items		\$849,996	
Mechanical					
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Air Cooled Condenser Replacement	Capital Renewal	1 Ea.	2	\$6,423	5214
Air Cooled Condenser Replacement	Capital Renewal	1 Ea.	2	\$20,946	5217
Air Handler HVAC Component Replacement	Capital Renewal	2 Ea.	2	\$290,079	5225
Air Handler HVAC Component Replacement	Capital Renewal	1 Ea.	2	\$145,040	5226
Air Handler HVAC Component Replacement	Capital Renewal	1 Ea.	2	\$145,040	5227
Air Handler HVAC Component Replacement	Capital Renewal	4 Ea.	2	\$455,426	5229
Air Handler HVAC Component Replacement	Capital Renewal	1 Ea.	2	\$113,856	5230
Air Handler HVAC Component Replacement	Capital Renewal	1 Ea.	2	\$85,959	5231
Air Handler HVAC Component Replacement	Capital Renewal	1 Ea.	2	\$85,959	5232
Air Handler HVAC Component Replacement	Capital Renewal	2 Ea.	2	\$86,327	5233
Note: vibration and noise					
Location: small gym					
Ductless Split System AC Replacement	Capital Renewal	1 Ea.	2	\$5,425	5215
Fan Coil HVAC Component Replacement	Capital Renewal	1 Ea.	2	\$11,109	5216
Gas Piping Replacement (SF Basis)	Capital Renewal	4,000 SF	2	\$138,701	5193
HVAC VAV Box Replacement	Capital Renewal	15 Ea.	2	\$58,108	5228
Mechanical / HVAC Piping / System Is Beyond Its Useful Life	Capital Renewal	128,186 SF	2	\$310,168	5224
Package DX Unit Replacement	Capital Renewal	1 Ea.	2	\$26,366	5218
Package DX Unit Replacement	Capital Renewal	1 Ea.	2	\$21,202	5219
Package DX Unit Replacement	Capital Renewal	2 Ea.	2	\$34,039	5221
Package DX Unit Replacement	Capital Renewal	1 Ea.	2	\$21,202	5222
Package DX Unit Replacement	Capital Renewal	2 Ea.	2	\$34,039	5223
Thru Wall AC Replacement	Capital Renewal	1 Ea.	2	\$2,875	5220
Kitchen Exhaust Hood Replacement	Capital Renewal	1 Ea.	3	\$11,191	5237
Large Diameter Exhausts/Hoods Replacement	Capital Renewal	5 Ea.	3	\$40,181	5235
Large Diameter Exhausts/Hoods Replacement	Capital Renewal	1 Ea.	3	\$8,036	5238
Small Diameter Exhausts/Hoods Replacement	Capital Renewal	4 Ea.	3	\$7,839	5234
Ceiling Exhaust Fan Replacement	Capital Renewal	1 Ea.	4	\$487	5236
Existing Controls Are Obsolete	Capital Renewal	128,186 SF	4	\$198,348	5213
	Sub Total for System	27 items		\$2,364,370	
Electrical	-				
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Electrical Transformer Replacement	Capital Renewal	3 Ea.	2	\$16,557	5259
Note: 20, 25, and 30 KVA	Capital Noticwal	J La.	_	ψ10,007	5203
20, 20, and 00 NV/					

M=A=P=P=S ©, Jacobs 2022








Electrical

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Electrical Transformer Replacement	Capital Renewal	3	Ea.	2	\$12,684	5261
Note: 9 and 10 KVA						
Electrical Transformer Replacement	Capital Renewal	3	Ea.	2	\$21,862	5262
Electrical Transformer Replacement	Capital Renewal	4	Ea.	2	\$23,676	5263
Electrical Transformer Replacement	Capital Renewal	1	Ea.	2	\$9,908	5264
Exterior Liquid Filled Transformer Replacement	Capital Renewal	1	Ea.	2	\$47,520	5483
Note: #993777						
Motor Control Center Replacement	Capital Renewal	1	Ea.	2	\$1,837	5256
Note: breakers tied in open position - may be abandoned (no loto show	n)					
Panelboard Replacement	Capital Renewal	2	Ea.	2	\$8,471	5265
Panelboard Replacement	Capital Renewal	5	Ea.	2	\$7,294	5266
Note: pp6, pp7, pp8, 10e						
Panelboard Replacement	Capital Renewal	1	Ea.	2	\$5,500	5267
Note: stage support beam is non-compliant with PNL clearance area	•					
Panelboard Replacement	Capital Renewal	1	Ea.	2	\$5,500	5268
Panelboard Replacement	Capital Renewal	3	Ea.	2	\$16,499	5269
Note: I1, pp4, pp2	•					
Panelboard Replacement	Capital Renewal	1	Ea.	2	\$13,891	5270
Panelboard Replacement	Capital Renewal	2	Ea.	2	\$18,745	5271
Note: lp2, lp3					¥ -, -	
Panelboard Replacement	Capital Renewal	4	Ea.	2	\$26,754	5272
Note: lp1, exit, lp6, lp7					¥ -, -	
Panelboard Replacement	Capital Renewal	1	Ea.	2	\$9.372	5273
Note: lp6. the majority of panel instructions have some necessary safet	•				* - / -	
safety labeling	, 5,54,4,755,754,557,5754,754,754,754,754,	godi dooo i		o 1.000000	, .oquou a.o c	to
Switchgear Replacement	Capital Renewal	1	Ea.	2	\$68,027	5257
Switchgear Replacement	Capital Renewal	1	Ea.	2	\$65,478	5258
Canopy Lighting Replacement	Capital Renewal	10	Ea.	3	\$20,830	5280
Exterior Mounted Building Lighting Replacement	Capital Renewal	14	Ea.	3	\$12,624	5281
Interior Power Wiring Replacement	Deferred Maintenance	128,186	SF	3	\$152,245	5283
Lighting Fixtures Replacement	Capital Renewal	128,186	SF	3	\$2,350,744	5282
Lightning Protection System Installation	Functional Deficiency	128,186	SF	3	\$100,102	5358
Note: no lightning protection installed						
Public Address System Replacement, Non-main Building	Deferred Maintenance	1	SF	3	\$1	5274
Note: it was reported that the PA was not working well in the gym						
	Sub Total for System	25	items		\$3,021,478	
Plumbing						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Water Heater Replacement	Capital Renewal		Ea.	2	\$5,719	5192
Plumbing / Domestic Water Piping System Is Beyond Its Useful Life	Capital Renewal	128,186		3	\$460,666	5194
Sanitary Sewer Piping Replacement	Capital Renewal	128,186		3	\$142,316	5195
Shower Replacement	Capital Renewal		Ea.	3	\$5,226	5205
Shower Replacement	Capital Renewal	10		3	\$13,065	
		39		3		
Toilet Replacement	Capital Renewal Capital Renewal			3	\$197,316 \$28,430	5206 5207
Urinal Replacement	Capital Renewal	21	∟a. Ea.	3 4	\$28,439 \$1,502	5207 5204
Custodial Mop Or Service Sink Replacement					\$1,592 \$22,024	5204
Refrigerated Water Cooler Replacement	Capital Renewal	10		4	\$22,024	5208
Replace classroom lavatory	Capital Renewal	40		4	\$102,580	
Replace classroom lavatory	Capital Renewal	16		4	\$41,032	
Replace classroom lavatory	Capital Renewal		Ea.	4	\$10,258	5211
Restroom Lavatories Plumbing Fixtures Replacement	Capital Renewal	29		4	\$78,772	5203
	Sub Total for System	13	items		\$1,109,003	








Fire and Life Sa	irety
------------------	-------

	Suloty						
Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
Emergency Lighting	System Replacement	Capital Renewal	128,186	SF	1	\$62,429	5279
Fire Alarm Panel Re	placement	Capital Renewal	1	Ea.	1	\$6,868	5278
Fire Alarm Replacem	nent	Capital Renewal	128,186	SF	1	\$203,536	5277
Security Alarm Repla	acement	Capital Renewal	128,186	SF	1	\$295,048	5276
		Sub Total for System	4	items		\$567,881	
Technology							
Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
Public Address Syste	em Head-End Requires Replacement	Functional Deficiency	1	Ea.	3	\$7,307	5275
		Sub Total for System	1	items		\$7,307	
Conveyances							
Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
Elevator Cab Replac	ement	Capital Renewal	1	Ea.	2	\$98,739	5191
		Sub Total for System	1	items		\$98,739	
Specialties							
Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
Metal Student Locke	rs Replacement	Capital Renewal		Ea.	4	\$375,053	
Note:	end of life	•					
Location	: corridors						
		Sub Total for System	1	items		\$375,053	
Crawlspace							
Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred Maintenance	381,459		5	\$448,157	6680
Note:	SOIL/DRAINAGE BELOW BUILDING - improve drainage - 68513 S	SF.					
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred Maintenance	31,758	Ea.	5	\$37,311	6681
Note:	PERIMETER SOIL RETAINERS - minor soil retainer repair - 1426 L	_F					
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred Maintenance	381,459	Ea.	5	\$448,157	6682
Note:	CRAWL SPACE ACCESS/VENTILATION - improve ventilation - 68	513					
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred Maintenance	58,461	Ea.	5	\$68,683	6683
Note:	CRAWL SPACE ACCESS/VENTILATION - repair access - 6 EA						
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred Maintenance	47,682	Ea.	5	\$56,019	6684
Note:	STANDARD FOUNDATIONS - minor mushroom repair - 68513 GS	F					
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred Maintenance	47,682	Ea.	5	\$56,019	6685
Note:	SUSPENDED FLOOR BEAMS - minor honeycombing repairs - 685	13 SF					
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred Maintenance	1,430,472	Ea.	5	\$1,680,591	6686
Note:	SUSPENDED FLOOR SLABS - structural analysis & repair - 6851	3 GSF					
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred Maintenance	155,895	Ea.	5	\$183,153	6687
Note:	CRAWL SPACE, EXPOSED PIPES - Repair pipe leaks, insulation a	and rustin pipes - 1 LS					
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred Maintenance	41,758	Ea.	5	\$49,059	6688
Note:	CRAWL SPACE, EXPOSED DUCTWORK - Replace rusting duct -	1 LS					
		Sub Total for System	9	items		\$3,027,152	
	ing 055A - Main building includes Administration Offices, Classro	•	97	items		\$13,698,265	
Ranging: 0	55B - Stand-Alone Classroom Buildinថ	9					
Interior							
Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID

Note: sagging grid, damaged tiles

Location: various locations







Interior

Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Vinyl Composition Tile Replacement	Capital Renewal	9,508 SF	4	\$77,754	5181
Note: end of life					
Location: various locations					
Interior Wall Repainting	Deferred Maintenance	10,000 SF Wall	5	\$22,463	5180
Note: scuffs, stains, and flaking					
Location: various locations					
Machaniael	Sub Total for System	3 items		\$123,938	
Mechanical					
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Air Cooled Condenser Replacement	Capital Renewal	1 Ea.	2	\$6,423	5246
Fan Coil Unit Replacement	Capital Renewal	1 Ea.	2	\$1,970	5247
Fan Coil Unit Replacement	Capital Renewal	8 Ea.	2	\$15,760	5248
Fan Coil Unit Replacement	Capital Renewal	1 Ea.	2	\$9,463	5249
Fan Coil Unit Replacement	Capital Renewal	1 Ea.	2	\$14,336	5250
Heat Pump HVAC Component Replacement	Capital Renewal	8 Ea.	2	\$71,261	5251
Heat Pump HVAC Component Replacement	Capital Renewal	1 Ea.	2	\$45,894	5252
Heat Pump HVAC Component Replacement	Capital Renewal	1 Ea.	2	\$45,894	5253
Existing Controls Are Obsolete	Capital Renewal	10,564 SF	4	\$16,346	5245
	Sub Total for System	9 items		\$227,346	
Electrical					
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Lightning Protection System Installation	Functional Deficiency	10,564 SF	3	\$8,250	5359
Note: no lightning protection installed					
Public Address System Replacement, Non-main Building	Deferred Maintenance	1 SF	3	\$1	5284
Note: it was reported that the PA system did not work well in "B" building					
	Sub Total for System	2 items		\$8,250	
Plumbing					
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Water Heater Replacement	Capital Renewal	1 Ea.	2	\$1,587	5239
Toilet Replacement	Capital Renewal	6 Ea.	3	\$30,356	5242
Urinal Replacement	Capital Renewal	4 Ea.	3	\$5,417	5243
Custodial Mop Or Service Sink Replacement	Capital Renewal	1 Ea.	4	\$796	5241
Refrigerated Water Cooler Replacement	Capital Renewal	1 Ea.	4	\$2,202	5244
Restroom Lavatories Plumbing Fixtures Replacement	Capital Renewal	10 Ea.	4	\$27,163	5240
	Sub Total for System	6 items		\$67,521	
Fire and Life Safety					
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Deficiency Fire Alarm Panel Replacement	Category Capital Renewal	Qty UoM 1 Ea.	Priority 1	Repair Cost \$6,868	ID 5288
				<u>.</u>	5288
Fire Alarm Panel Replacement Fire Alarm Replacement	Capital Renewal	1 Ea.	1	\$6,868 \$16,774	5288
Fire Alarm Panel Replacement	Capital Renewal Capital Renewal	1 Ea. 10,564 SF	1	\$6,868	5288 5287
Fire Alarm Panel Replacement Fire Alarm Replacement	Capital Renewal Capital Renewal Capital Renewal	1 Ea. 10,564 SF 10,564 SF	1	\$6,868 \$16,774 \$24,315	5288 5287
Fire Alarm Panel Replacement Fire Alarm Replacement Security Alarm Replacement Technology	Capital Renewal Capital Renewal Capital Renewal Sub Total for System	1 Ea. 10,564 SF 10,564 SF 3 items	1	\$6,868 \$16,774 \$24,315	5288 5287
Fire Alarm Panel Replacement Fire Alarm Replacement Security Alarm Replacement	Capital Renewal Capital Renewal Capital Renewal Sub Total for System Category	1 Ea. 10,564 SF 10,564 SF	1 1 1	\$6,868 \$16,774 \$24,315 \$47,957	5288 5287 5286
Fire Alarm Panel Replacement Fire Alarm Replacement Security Alarm Replacement Technology Deficiency	Capital Renewal Capital Renewal Capital Renewal Sub Total for System Category Functional Deficiency	1 Ea. 10,564 SF 10,564 SF 3 items	1 1 1	\$6,868 \$16,774 \$24,315 \$47,957 Repair Cost \$7,307	5288 5287 5286
Fire Alarm Panel Replacement Fire Alarm Replacement Security Alarm Replacement Technology Deficiency Public Address System Head-End Requires Replacement	Capital Renewal Capital Renewal Capital Renewal Sub Total for System Category Functional Deficiency Sub Total for System	1 Ea. 10,564 SF 10,564 SF 3 items Qty UoM 1 Ea.	1 1 1	\$6,868 \$16,774 \$24,315 \$47,957 Repair Cost \$7,307 \$7,307	5288 5287 5286
Fire Alarm Panel Replacement Fire Alarm Replacement Security Alarm Replacement Technology Deficiency	Capital Renewal Capital Renewal Capital Renewal Sub Total for System Category Functional Deficiency Sub Total for System	1 Ea. 10,564 SF 10,564 SF 3 items Qty UoM 1 Ea. 1 items	1 1 1	\$6,868 \$16,774 \$24,315 \$47,957 Repair Cost \$7,307	5288 5287 5286

M*A*P*P*S ©, Jacobs 2022 13



Dobie MS - Life Cycle Summary Yrs 1-10 Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Parking Lot Pavement	Asphalt		97	CAR	\$140,728	4
Fences and Gates	Fencing - Chain Link (8-10 Ft)		3,580	LF	\$280,475	5
Fences and Gates	Fencing - Ornamental, Iron		200	LF	\$15,696	5
Fences and Gates	Competition Style Track		1	Ea.	\$294,838	5
Parking Lot Pavement	Concrete		19	CAR	\$46,853	5
Roadway Pavement	Asphalt Driveways		38,420	SF	\$247,057	5
Pedestrian Pavement	Sidewalks - Concrete		11,750	SF	\$133,095	5
		Sub Total for System	7	items	\$1,158,741	
Electrical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Parking Lot Lighting	Pole Lighting		6	Ea.	\$34,918	5
		Sub Total for System	1	items	\$34,918	
		Sub Total for Building -	8	items	\$1,193,659	

$\textbf{Building: 055A-Main building includes Administration Offices, Classrooms, Cafeteria, \& \ Gym.}$

Exterior

Uniformat Description	LC Type Description		Qty UoM	Repair Cost Remain	ning Life
Exterior Window Wall	Storefront / Curtain Wall (Bldg SF)		6,409 SF	\$154,978	5
Exterior Operating Windows	Aluminum - Windows per SF		570 SF	\$56,844	5
Exterior Entrance Doors	Steel - Insulated and Painted		19 Door	\$70,433	5
Exterior Entrance Doors	Storefront Doors - Glass/Aluminum		17 Door	\$67,473	10
		Sub Total for System	4 items	\$349 728	


Interior

Interior						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Wall Painting and Coating	Painting/Staining (Bldg SF)	,	97,421	SF	\$436,536	2
Compartments and Cubicles	Toilet Partitions		25	Stall	\$50,412	2
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles		32,047	SF	\$108,215	3
Suspended Plaster and	Painted ceilings		12,819	SF	\$26,697	3
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles		64,093	SF	\$216,426	5
Acoustical Suspended Ceilings	Ceiling Exposed Metal Structure		12,819	SF	\$11,088	5
Athletic Flooring	Athletic/Sport Flooring		1,282	SF	\$19,668	5
Carpeting	Carpet		1,282	SF	\$16,230	5
Tile Flooring	Ceramic Tile		16,664	SF	\$294,408	5
Tile Flooring	Quarry Tile		2,564	SF	\$70,091	5
Resilient Flooring	Vinyl Composition Tile Flooring		51,274	SF	\$419,304	5
Wood Flooring	Wood Flooring - All Types		12,819	SF	\$276,120	5
Interior Swinging Doors	Metal Door (Steel)		21	Door	\$60,770	5
Interior Swinging Doors	Wooden Door		90	Door	\$168,804	5
Interior Coiling Doors	Interior Overhead Doors		2	Ea.	\$10,573	5
Interior Door Supplementary Components	Door Hardware		113	Door	\$167,761	5
Wall Painting and Coating	Painting/Staining (Bldg SF)		97,421	SF	\$436,536	9
Interior Swinging Doors	Storefront door (Aluminum/Glass)		2	Door	\$7,242	10
		Sub Total for System	18	items	\$2,796,881	

Mechanical

Uniformat Description	LC Type Description	Qty Uo	M Repair Cost	Remaining Life
Heat Generation	Boiler - Copper Tube (4800 MBH)	2 Ea	\$298,342	10
Heating System Supplementary Components	Controls - Electronic (Bldg.SF)	128,186 SF	\$198,348	10
Central Cooling	Cooling Tower - Metal (300 Tons)	2 Ea	\$115,657	10
Other HVAC Distribution Systems	VFD (40 HP)	2 Ea	\$27,872	10
Other HVAC Distribution Systems	VFD (40 HP)	2 Ea	\$27,872	10
Other HVAC Distribution Systems	VFD (15 HP)	3 Ea	\$22,676	10
Other HVAC Distribution Systems	VFD (7.5 HP)	2 Ea	\$10,446	10
Facility Hydronic Distribution	Pump - 5HP	2 Ea	\$13,700	10








			ca	

Definite December	Mconamoai						
Particip (Privance Distribution Prune - 500P (-Ea) Fallis (Privance Distribution Prune - 500P (-Ea) Fallis (Privance Distribution Prune - 200P (-Ea) Fallis	Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Paper Pape	Facility Hydronic Distribution	Pump - 50HP - (Ea.)		2	Ea.	\$115,412	10
Finalize Africa Microse Centrologies (1.6 mg state Africa Microse Micros	Facility Hydronic Distribution	Pump - 50HP - (Ea.)		2	Ea.	\$115,412	10
Electrical Sub-Total for System 1 En. \$11.10 10 10 10 10 10 10 10				2	Ea.		10
	* *						
Description 1.0 Type Description Destitution Parelle (400 Ample) 1 Ea. \$15,005 5			Sub Total for System				
Uniform Description Uniform Description Descript			5 m 7 5 m 7 5 7 5 1 5 1 5 1 5 1 5 1 5 1 5 1 5 1 5			4000,001	
Description Description Pares (400 Amps) 1 Em. \$16.005 5	Electrical						
Notes 1993 - 490 V Peneband 120208 400A 1 Em. \$10,000 5 1 Em. \$10,000	Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Power Distribution	Power Distribution	Distribution Panels (400 Amps)		1	Ea.	\$16,905	5
Note: 1908 Pane Board 120/208 225A	No	te: 1999 - 480 V					
Power Distribution	Power Distribution	Panelboard - 120/208 400A		1	Ea.	\$12,342	5
Note: 1986 Power Distribution Note: 20101 Power Distribution Note: 20101 Power Distribution Pameboard - 277/480 100A Sab Total for System Sab	No	te: 1999					
Pame	Power Distribution	Panelboard - 120/208 225A		2	Ea.	\$10,999	5
Note: 2001 Power Distribution Panelboard - 277/480 100A Note: 2001 Sub Total for System Sitems \$74,221 System Syst	No	te: 1999					
Pame Describution Pame Description Pame	Power Distribution	Panelboard - 120/208 100A		5	Ea.	\$13,910	5
Note: 2001 Sub Total for System 5 Items \$74,221	No	vte: 2001					
Note: 2001 Sub Total for System 5 Items \$74,221	Power Distribution	Panelboard - 277/480 100A		3	Ea.	\$20.065	5
Plumbing						* -,	
Delimbing Description			Sub Total for System	5	items	\$74.221	
Dunoses Description CL Type Description Valer Flateric - 30 gallon 2 Ea. \$4.271 10	Diametria		oub rotal for dystem	·	itomo	Ψ1-4, 22 1	
Domestic Water Equipment Water Heater - Electric - 30 gallon 2 Ea. \$4.271 10	Piumbing						
Domestic Water Equipment Water Heater - Electric - 120 gallon 1 Ea. \$5,719 10	Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Sub Total for System Passenger elevator cab finishes Sub Total for System Sub Total	Domestic Water Equipment	Water Heater - Electric - 30 gallon		2	Ea.	\$4,271	10
Conveyances	Domestic Water Equipment	Water Heater - Electric - 120 gallon		1	Ea.	\$5,719	10
Conveyances	Domestic Water Equipment	Water Heater - Gas - 100 Gallon		2	Ea.	\$12,768	10
Dufformat Description LC Type Description Passenger elevator cab finishes Sub Total for System 1 Items \$23,954 5 5 5 5 5 5 5 5 5			Sub Total for System	3	items	\$22,757	
Dufformat Description LC Type Description Passenger elevator cab finishes Sub Total for System 1 Items \$23,954 5 5 5 5 5 5 5 5 5	Conveyances						
Passenger elevator cab finishes Sub Total for System 1 items \$23,954 5	-						
Sub Total for System 1 Items \$23,954 Specialties Uniformat Description LC Type Description LC Type Description Qdy UoM Repair Cost Remaining Casework Lockers, Gym 1,306 Ea. \$634,056 5 Fixed Multiple Seating Bleachers 800 Seat \$330,467 5 Sub Total for Building 055A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym. 3 Items \$1,316,617 1 Building: 055B - Stand-Alone Classroom Building Exterior Uniformat Description LC Type Description Qt UoM Repair Cost Remaining Exterior Furtance Doors Steel - Insulated and Painted 2 Door \$7,414 5 Exterior Furtance Doors Steel - Insulated and Painted 2 Door \$7,414 5 Interior Uniformat Description LC Type Description Qt UoM Repair Cost Remaining Exterior Interior Description LC Type Description Qt Uo	· · · · · · · · · · · · · · · · · · ·						
Carework Fixed Cabinetry 40 Repair Cost Remaining Casework Fixed Cabinetry 40 Room \$352,075 2 Casework Lockers, Gym 1,006 Ea. \$834,056 5 Rived Multiple Seating Bleachers 800 Seat \$330,487 5 Rived Multiple Seating Bleachers 800 Seat \$330,487 5 Rived Multiple Seating Bleachers 800 Total for System 3 Items \$1,316,617 5 Rived Multiple Seating 800 Seat \$330,487 5 Rived Multiple Seating 800 Seat 8	Elevators	Passenger elevator cab finishes					5
Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Casework Fixed Cathinetry 40 Room \$52,075 2 Casework Lockers, Gym 1,306 Ea. \$634,056 5 Fixed Multiple Seating Bleachers 800 Seat \$330,487 5 Sub Total for System 3 items \$1,316,617 5 Sub Total for Building 0555A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym. 46 items \$5,569,850 5 Building: 0555B - Stand-Alone Classroom Building Exterior Uniformat Description LC Type Description Clay UoM Repair Cost Remaining Exterior Coperating Windows Aluminum - Windows per SF \$F \$449 5 Exterior Coperating Windows Aluminum - Windows per SF \$E \$E \$400 \$F \$440 5 Exterior Coperating Windows Aluminum - Windows per SF \$E \$E \$E \$E \$E \$E \$E <			Sub Total for System	1	items	\$23,954	
Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Casework Fixed Cathinetry 40 Room \$52,075 2 Casework Lockers, Gym 1,306 Ea. \$634,056 5 Fixed Multiple Seating Bleachers 800 Seat \$330,487 5 Sub Total for System 3 items \$1,316,617 5 Sub Total for Building 0555A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym. 46 items \$5,569,850 5 Building: 0555B - Stand-Alone Classroom Building Exterior Uniformat Description LC Type Description Clay UoM Repair Cost Remaining Exterior Coperating Windows Aluminum - Windows per SF \$F \$449 5 Exterior Coperating Windows Aluminum - Windows per SF \$E \$E \$400 \$F \$440 5 Exterior Coperating Windows Aluminum - Windows per SF \$E \$E \$E \$E \$E \$E \$E <	Specialties						
Parametric Par	-	LC Type Description		Qtv	UoM	Repair Cost	Remaining Life
Casework Lockers, Gym 1,306 Ea. \$634,056 5 Fixed Multiple Seating Bleachers 800 Seat \$330,487 5 Sub Total for System 3 Items \$1,316,617 5 Sub Total for Building 055A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym. 46 Items \$5,569,850 Building: 055B - Stand-Alone Classroom Building Exterior Uniformal Description LC Type Description Qty UoM Repair Cost Remaining Exterior Operating Windows Aluminum - Windows per SF 5 SF \$499 5 Exterior Entrance Doors Steel - Insulated and Painted 3ub Total for System 2 Door \$7,414 5 Exterior Entrance Doors LC Type Description CT Type Description Qty UoM Repair Cost Remaining Uniformat Description LC Type Description (Bidg SF) 10,036 SF \$44,971 2 Compantments and Cubicles Tollet Partitions							
Sub Total for Building 055A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym. 31 tems \$1,316,617 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$1,569,855 \$							
Sub Total for Subtem 3 items \$1,316,617							
Sub Total for Building 055A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym. 46 tems \$5,569,850	Tixed Multiple Seating	Dieactiers	Sub Total for System				3
Exterior	Sub Total for Building OFFA	Main building includes Administration Offices					
Exterior Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Exterior Operating Windows Aluminum - Windows per SF 5 SF \$499 5 Exterior Entrance Doors Steel - Insulated and Painted 2 Door \$7,414 5 Sub Total for System 2 items \$7,913 7 Interior Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Wall Painting and Coating Painting/Staining (Bldg SF) 10,036 SF \$44,971 2 Acoustical Suspended Ceilings Cellings - Acoustical Tiles 10,036 SF \$33,889 3 Compartments and Cubicles Toilet Partitions 9 Stall \$11,818 5 Interior Swinging Doors Metal Door (Steel) 528 SF \$9,328 5 Interior Swinging Doors Metal Door (Steel) 4 Door \$11,575 5 Interior Swinging Doors Metal Door (Steel) 10,036 SF \$44,971			, Classicoms, Caleteria, & Gym.	40	Itellis	φ3,30 3 ,030	
Duiformat Description LC Type Description Qty UoM Repair Cost Remaining	Building: 055B - Stand	Alone Classroom Building					
Duiformat Description LC Type Description Qty UoM Repair Cost Remaining	Exterior						
Exterior Operating Windows Aluminum - Windows per SF \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$							
Exterior Entrance Doors Steel - Insulated and Painted 2 Door \$7,414 5 Sub Total for System 2 items \$7,913 5 Interior Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Wall Painting and Coating Painting/Staining (Bldg SF) 10,036 SF \$44,971 2 Acoustical Suspended Ceilings Ceilings - Acoustical Tiles 10,036 SF \$33,889 3 Compartments and Cubicles Toilet Partitions 9 Stall \$18,148 5 Tile Flooring Ceramic Tile 528 SF \$9,328 5 Interior Swinging Doors Metal Door (Steel) 4 Door \$11,575 5 Interior Swinging Doors Wooden Door 14 Door \$26,258 5 Interior Door Supplementary Components Door Hardware 10,006 SF \$44,971 9 Mechanical Sub Total for System 8 items \$215,863 5 Exhaust Air	· · · · · · · · · · · · · · · · · · ·						
Interior Sub Total for System 2 items \$7,913 Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Wall Painting and Coating Painting/Staining (Bldg SF) 10,036 SF \$44,971 2 Acoustical Suspended Ceilings Ceilings - Acoustical Tiles 10,036 SF \$33,889 3 Compartments and Cubicles Toilet Partitions 9 \$tall \$18,148 5 Tile Flooring Ceramic Tile 528 SF \$9,328 5 Interior Swinging Doors Metal Door (Steel) 4 Door \$11,575 5 Interior Door Supplementary Components Mooden Door 14 Door \$26,258 5 Mall Painting and Coating Painting/Staining (Bldg SF) 10,036 SF \$44,971 9 Mechanical Uniformat Description LC Type Description Ot Uniformat Description Qt UoM Repair Cost Remaining Exhaust Air Reating System Supplementary Controls - Electronic (Exterior Operating Windows	Aluminum - Windows per SF		5	SF	\$499	5
Interior Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Wall Painting and Coating Painting/Staining (Bldg SF) 10,036 SF \$44,971 2 Acoustical Suspended Ceilings Ceilings - Acoustical Tiles 10,036 SF \$33,889 3 Compartments and Cubicles Toilet Partitions 9 Stall \$18,148 5 Tile Flooring Ceramic Tile 528 SF \$9,328 5 Interior Swinging Doors Metal Door (Steel) 4 Door \$11,575 5 Interior Swinging Doors Wooden Door 14 Door \$26,258 5 Interior Door Supplementary Components Door Hardware 18 Door \$26,723 5 Wall Painting and Coating Painting/Staining (Bldg SF) Sub Total for System 8 \$44,971 9 Mechanical Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Exhaust Air Roof Exhaust Fan - Large </td <td>Exterior Entrance Doors</td> <td>Steel - Insulated and Painted</td> <td></td> <td>2</td> <td>Door</td> <td>\$7,414</td> <td>5</td>	Exterior Entrance Doors	Steel - Insulated and Painted		2	Door	\$7,414	5
Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Wall Painting and Coating Painting/Staining (Bldg SF) 10,036 SF \$44,971 2 Acoustical Suspended Ceilings Ceilings - Acoustical Tiles 10,036 SF \$33,889 3 Compartments and Cubicles Toilet Partitions 9 Stall \$18,148 5 Tille Flooring Ceramic Tile 528 SF \$9,328 5 Interior Swinging Doors Metal Door (Steel) 4 Door \$11,575 5 Interior Door Supplementary Components Door Hardware 18 Door \$26,258 5 Wall Painting and Coating Painting/Staining (Bldg SF) 10,036 SF \$44,971 9 Mechanical Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Exhaust Air Roof Exhaust Fan - Large 2 Ea. \$16,072 5 Heating System Supplementary Controls - Electronic (Bldg.SF) <td< td=""><td></td><td></td><td>Sub Total for System</td><td>2</td><td>items</td><td>\$7,913</td><td></td></td<>			Sub Total for System	2	items	\$7,913	
Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Wall Painting and Coating Painting/Staining (Bldg SF) 10,036 SF \$44,971 2 Acoustical Suspended Ceilings Ceilings - Acoustical Tiles 10,036 SF \$33,889 3 Compartments and Cubicles Toilet Partitions 9 Stall \$18,148 5 Tille Flooring Ceramic Tile 528 SF \$9,328 5 Interior Swinging Doors Metal Door (Steel) 4 Door \$11,575 5 Interior Door Supplementary Components Door Hardware 18 Door \$26,258 5 Wall Painting and Coating Painting/Staining (Bldg SF) 10,036 SF \$44,971 9 Mechanical Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Exhaust Air Roof Exhaust Fan - Large 2 Ea. \$16,072 5 Heating System Supplementary Controls - Electronic (Bldg.SF) <td< td=""><td>Interior</td><td></td><td></td><td></td><td></td><td></td><td></td></td<>	Interior						
Wall Painting and Coating Painting/Staining (Bldg SF) 10,036 SF \$44,971 2 Acoustical Suspended Ceilings Ceilings - Acoustical Tiles 10,036 SF \$33,889 3 Compartments and Cubicles Toilet Partitions 9 Stall \$18,148 5 Tile Flooring Ceramic Tile 528 SF \$9,328 5 Interior Swinging Doors Metal Door (Steel) 4 Door \$11,575 5 Interior Swinging Doors Wooden Door 14 Door \$26,258 5 Interior Door Supplementary Components Door Hardware 18 Door \$26,723 5 Wall Painting and Coating Painting/Staining (Bldg SF) 10,036 SF \$44,971 9 Mechanical Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Exhaust Air Roof Exhaust Fan - Large 2 Ea. \$16,072 5 Heating System Supplementary Controls - Electronic (Bldg,SF) 10,564 SF	Uniformat Description	LC Type Description		Otv	HoM	Renair Cost	Remaining Life
Acoustical Suspended Ceilings Ceilings - Acoustical Tiles 10,036 SF \$33,889 3 Compartments and Cubicles Toilet Partitions 9 Stall \$18,148 5 Tile Flooring Ceramic Tile 528 SF \$9,328 5 Interior Swinging Doors Metal Door (Steel) 4 Door \$11,575 5 Interior Swinging Doors Wooden Door 14 Door \$26,258 5 Interior Door Supplementary Components Door Hardware 18 Door \$26,723 5 Wall Painting and Coating Painting/Staining (Bldg SF) 10,036 SF \$44,971 9 Mechanical Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Exhaust Air Roof Exhaust Fan - Large 2 Ea. \$16,072 5 Heating System Supplementary Controls - Electronic (Bldg.SF) 10,564 SF \$16,346 10	•					<u>.</u>	
Compartments and Cubicles Toilet Partitions 9 Stall \$18,148 5 Tile Flooring Ceramic Tile 528 SF \$9,328 5 Interior Swinging Doors Metal Door (Steel) 4 Door \$11,575 5 Interior Swinging Doors 14 Door \$26,258 5 Interior Door Supplementary Components Door Hardware 18 Door \$26,723 5 Wall Painting and Coating Painting/Staining (Bldg SF) 10,036 SF \$44,971 9 Mechanical Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Exhaust Air Roof Exhaust Fan - Large 2 Ea. \$16,072 5 Heating System Supplementary Controls - Electronic (Bldg.SF) 10,564 SF \$16,346 10							
Tile Flooring Ceramic Tile 528 SF \$9,328 5 Interior Swinging Doors Metal Door (Steel) 4 Door \$11,575 5 Interior Swinging Doors Wooden Door 14 Door \$26,258 5 Interior Door Supplementary Components Door Hardware 18 Door \$26,258 5 Wall Painting and Coating Painting/Staining (Bldg SF) 10,036 SF \$44,971 9 Sub Total for System 8 items \$215,863 1 Mechanical Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Exhaust Air Roof Exhaust Fan - Large 2 Ea. \$16,072 5 Heating System Supplementary Controls - Electronic (Bldg.SF) 10,564 SF \$16,346 10	·	·		•			
Interior Swinging Doors Metal Door (Steel) 4 Door \$11,575 5 Interior Swinging Doors Wooden Door 14 Door \$26,258 5 Interior Door Supplementary Components Door Hardware 18 Door \$26,723 5 Wall Painting and Coating Painting/Staining (Bldg SF) 10,036 SF \$44,971 9 Wechanical Sub Total for System 8 Items \$215,863 Wechanical Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Exhaust Air Roof Exhaust Fan - Large 2 Ea. \$16,072 5 Heating System Supplementary Controls - Electronic (Bldg.SF) 10,564 SF \$16,346 10 Controls - Electronic (Bldg.SF) 10,564 SF 10,564 10 Controls - Electronic (Bldg.SF) 10,564 10 Controls - Electronic (Bldg.SF) 10,564 10 Controls - Electroni	•						
Interior Swinging Doors Wooden Door \$26,258 5 Interior Door Supplementary Components Door Hardware 18 Door \$26,723 5 Wall Painting and Coating Painting/Staining (Bldg SF) 10,036 SF \$44,971 9 Mechanical Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Exhaust Air Roof Exhaust Fan - Large 2 Ea. \$16,072 5 Heating System Supplementary Controls - Electronic (Bldg.SF) 10,564 SF \$16,346 10	•						
Interior Door Supplementary Components Door Hardware 18 Door \$26,723 5 Wall Painting and Coating Painting/Staining (Bldg SF) 10,036 SF \$44,971 9 Sub Total for System 8 Items \$215,863 Mechanical Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Exhaust Air Roof Exhaust Fan - Large 2 Ea. \$16,072 5 Heating System Supplementary Controls - Electronic (Bldg.SF) 10,564 SF \$16,346 10		, ,					
Wall Painting and Coating Painting/Staining (Bldg SF) 10,036 SF \$44,971 9 9 Mechanical Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Remaining Exhaust Air Roof Exhaust Fan - Large 2 Ea. \$16,072 5 Heating System Supplementary Controls - Electronic (Bldg.SF) 10,564 SF \$16,346 10	Interior Swinging Doors	Wooden Door		14	Door	\$26,258	
Sub Total for System 8 items \$215,863 Mechanical Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Exhaust Air Roof Exhaust Fan - Large 2 Ea. \$16,072 5 Heating System Supplementary Controls - Electronic (Bldg.SF) 10,564 SF \$16,346 10	Interior Door Supplementary Component	s Door Hardware		18	Door	\$26,723	5
Mechanical Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Exhaust Air Roof Exhaust Fan - Large 2 Ea. \$16,072 5 Heating System Supplementary Controls - Electronic (Bldg.SF) 10,564 SF \$16,346 10	Wall Painting and Coating	Painting/Staining (Bldg SF)		10,036	SF	\$44,971	9
Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Exhaust Air Roof Exhaust Fan - Large 2 Ea. \$16,072 5 Heating System Supplementary Controls - Electronic (Bldg.SF) 10,564 SF \$16,346 10			Sub Total for System	8	items	\$215,863	
Uniformat Description LC Type Description Qty UoM Repair Cost Remaining Exhaust Air Roof Exhaust Fan - Large 2 Ea. \$16,072 5 Heating System Supplementary Controls - Electronic (Bldg.SF) 10,564 SF \$16,346 10	Mechanical						
Exhaust Air Roof Exhaust Fan - Large 2 Ea. \$16,072 5 Heating System Supplementary Controls - Electronic (Bldg.SF) 10,564 SF \$16,346 10		LC Type Description		04:	HoM	Poneir Cont	Pomoining Life
Heating System Supplementary Controls - Electronic (Bldg.SF) 10,564 SF \$16,346 10	· · · · · · · · · · · · · · · · · · ·						
·		Controls - Electronic (Bldg.SF)		10,564	SF	\$16,346	10
Sub Total for System 2 items \$32,419	1		Sub Total for System	2	items	\$32.410	

M•A•P•P•S ©, Jacobs 2022 15







Electrical

Uniformat Description		LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Power Distribution		Panelboard - 120/208 225A		1	Ea.	\$5,500	5
	Note:	2000					
Power Distribution		Panelboard - 277/480 400A		1	Ea.	\$13,891	5
	Note:	2000					
Lighting Fixtures		Light Fixtures (Bldg SF)		10,564	SF	\$193,728	5
Power Distribution		Power Wiring		10,564	SF	\$12,547	5
			Sub Total for System	4	items	\$225,665	
Plumbing							
Uniformat Description		LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Plumbing Fixtures		Classroom Lavatory		7	Ea.	\$17,951	5
Domestic Water Equipment		Water Heater - Electric - 20 gallon		2	Ea.	\$3,173	9
Domestic Water Equipment		Water Heater - Electric - 20 gallon		1	Ea.	\$1,587	10
			Sub Total for System	3	items	\$22,711	
Specialties							
Uniformat Description		LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Casework		Fixed Cabinetry		8	Room	\$70,415	1
			Sub Total for System	1	items	\$70,415	
		Sub Total for Building 055B - S	Stand-Alone Classroom Building	20	items	\$574,986	
			Total for: Dobie MS	74	items	\$7,338,496	



Supporting Photos

General Site Photos



Restroom partition walls past useful life



Stained and sagging acoustic ceiling system



Aged classroom wall paint



Gym wall paint is beyond useful life



Buckling wood floors



Hallway lockers beyond useful life

M•A•P•P•S ©, Jacobs 2022 17

Facility Condition Assessment

Austin ISD - Dobie MS





Rubber stairs are worn and torn



Restrooms wall tiles past useful life



Aged exterior walls



Obstructed electrical panels



Electrical panels are past useful life

M*A*P*P*S ©, Jacobs 2022 18