

Educational Suitability Summary Report

McCallum High School

Date: 01/28/2021 Score 50% Unsatisfactory

McCallum High School currently serves an enrollment of approximately 1,840 students in north central Austin. The campus serves as AISD's Fine Arts Academy and is open to all students in AISD who wish to attend, provided they are accepted through the admissions process. The original campus was built in 1953, with a new stand-alone addition constructed in 2011 to serve the Fine Arts Academy. The campus consists of approximately 216,000 square feet on 31 acres.

In addition to the Fine Arts Academy, McCallum offers general education coursework and CTE programs including Engineering, Accounting, Animation, Commercial Photography, A/V Production, Graphic Design and Exercise Science. The school has a robust athletics department, and the current facility size is creating issues in holding/scheduling games, especially in the main gymnasium.

The design of the original building provides access to daylight for all the exterior-facing studios, however the building lacks flexibility and does not allow for the types of spaces needed to teach classes at the current AISD standards. Studios are set up for rows of desks facing a single instructor and lack the infrastructure or flexible furniture to allow for a variety of seating arrangements.

Interview Overview

The interview was conducted via online conference call with Principal Nicole Griffith, Assistant Principal Gabe Reyes, Fine Arts Academy Director Heather Ramsay and Building Manager Camille Nix. Athletics Department Chair Tom Gammerdinger and CTE Department Chair Audrea Moyers joined to discuss conditions specific to their departments. McCallum High School has an important historical legacy, and there are artifacts that the school would like to display, including the Knight tile mural at the main office donated by the class of 1969 as well as murals on the building exterior and in the courtyard.

The interview highlighted many programs that are not in suitable spaces. McCallum is the designated Fine Arts magnet school for the district, yet two of its majors (guitar and piano) are housed in portables. There is no designated facility for the dance program, though it is slated to be added in 2022 with funding from a prior bond. The Fine Arts Academy needs space to expand to increase its course offerings, including a dedicated drama scene shop, a dedicated computer lab, and dedicated studios for music theory, music history and art history.

Athletics is a large area of concern. The competition gym spectator seating is inadequately sized and is located on one side of the gym, which creates problems when seating spectators from both schools together. They need to be able to run games concurrently to keep games from running too late, but the competition gym is the only gym with space for seating, and spectators for games in the practice gym end up standing against the walls.

CTE is another large area of concern. All but one of the programs are in spaces of inadequate size

Perkins&Will

Educational Suitability Summary Report

McCallum High School

and infrastructure. The campus currently offers programs in Business, Engineering, Accounting, Animation, Commercial Photography, A/V Production, Graphic Design and Exercise Science.

The school mostly supports the 6 C's through programming. The 6 C's are being hindered by many aspects of the school's infrastructure, including lack of collaboration space/flex space. The studios do not support any configuration but a lecture setup and there is no breakout space for group projects. The school also lacks teacher collaboration spaces (e.g., dedicated PLCs).



Assessment Findings

The Educational Suitability Assessment of McCallum High School earned a 50% overall score and places the campus in a category of Unsatisfactory. The assessment consists of seven General Building categories and eight Academic categories to determine areas that need more attention.

Unsatisfactory Categories (36-50%):

General Building

Score is unsatisfactory.

The cafeteria, gym and library cannot be accessed without allowing full school access, and there is no dedicated community meeting room. The general appearance of the school is aged, but not in disrepair.

Security

Score is unsatisfactory.



Score is unsatisfactory.

Sound from corridors and adjacent studios is audible in studios. Artificial lighting is adequate in studios in newer building, and poor quality in original building. There is evidence of rats and raccoons in some locations as well as a recurring sewage odor in one wing of the building.

Controllability of Systems

Score is unsatisfactory.

Each studio has individual temperature controls but most do not work. There is very little HVAC control and many windows do not open. Shades are provided to control natural light but are in poor condition. Lighting controls in studios are not dimmable; alternating rows of lights switch off when dimmed lighting is desired.

Educational Suitability Summary Report

McCallum High School

Academic & Learning

Score is unsatisfactory.

Majority of studios are too small and lack adequate storage space. Academic neighborhoods do not have any breakout rooms or open collaboration spaces and do not provide opportunities for students to work independently or to collaborate in groups of varying sizes. The campus lacks a dedicated maker space.

CTE and Career Connected Learning

Score is unsatisfactory.

Majority of CTE programs do not have adequate studio, lab or storage space for a campus of this size.

Food Services

Score is unsatisfactory.

The serving line is inadequately sized to be functional, and the food service manager's desk is located within the kitchen. The designated manager's office is currently being used as a storage closet.

Media Resources

Score is unsatisfactory.

The library has limited access and lacks transparency to the rest of the school. There are no breakout rooms or flexible furniture to support group study nor are there quiet spaces for individual study located within the library.

Technology

Score is unsatisfactory.

There is one type of instructional technology present in each studio. Studios located in the original building lack adequate outlets to support digital devices. There is no digital media signage in the reception area.

Administration Spaces

Score is unsatisfactory.

. The

administrative area lacks acoustic privacy in spaces that require it. The conference room for parent use is located toward the back of the administrative suite and is difficult to find. The admin spaces are not designed to encourage collaboration. The registrar and data processors area is not located in main office. There is not an adequate wait area for parents, and it does not have a welcoming feel.

Average Categories (51-65%):

Furniture, Fixtures, Equipment

Score is average.

Furniture is not new but is in good condition. The furniture is reconfigurable but is cumbersome to move. Some studios have separate tables and chairs, but other studios are furnished with chair desks combinations.

Visual and Performing Arts

Perkins&Will

Educational Suitability Summary Report

McCallum High School

Score is average.

Orchestra rehearsal space is too small to function well. Dance spaces are small and located in spaces borrowed or shared with other programs. A new dance studio was approved with the 2017 bond program. Two specialty arts programs are currently housed in a portable.

Athletics and Wellness

Score is average.

Exterior fields are not in good condition and require upkeep from the coaches. There is no site lighting, which makes practices difficult. The campus lacks a swimming pool but has an agreement to share facilities with the University of Texas. The competition gym is undersized, and the audience space is too small and is located all on one side of the gym. The adjacent practice gym is regularly used for competition to allow better scheduling of games but has no audience space. Neither gym has access from the exterior of the building.

Satisfactory Categories (66-80%):

Exterior

Score is satisfactory.

Buses, cars and pedestrians are separate, but the stack space is small due to site being landlocked. Signage is visible but not in good condition. The school notes parking is not adequate and students have to cross the road to access the main parking lot, which is a safety concern.

Outdoor Learning and Activity

Score is satisfactory.

Outdoor studios include one small solar studio. One larger covered area is provided with fixed tables and attached seats but little support for a true learning space; no power or screens provided, and seating is not ideal for learning. The furniture prevents a class or science lab from being held there. The learning garden is disconnected from other outdoor learning areas and in poor condition. No rain garden, rain collection cisterns or nature trails are present.



Exterior of school is dated, but in good condition.



Main Entry is small and has a low ceiling and dated lighting.



Corridors are adequate width for student circulation.




Outdoor solar studio.



Outdoor Courtyard: Not directly accessible from studios and not accessible from outside building, so mower must be brought through school to maintain courtyard. No shade and inadequate seating for outdoor learning.



Media Center: Library in good condition, but most furniture is not reconfigurable or easily movable. No breakout rooms or individual study spaces.



Typical studio in original building. No furniture flexibility or opportunity to work in small groups, lack of storage. Blinds are inconsistent within studios.



Science Lab Renovation: Adequate space, storage and prep area.




Competition Gym: Spectator bleachers located on one side of gym only.



Backstage at MAC: Lacks dedicated scene shop and storage.

McCallum High School



Wrestling gym shares space with dance program, drill team, cheer and sometimes piano.



Outdoor Studio: Generous size and well shaded. Furniture not flexible, no visual display board.



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

General Building

School N	lame							Walk Attendees:	Date:	
McCallu	m HS							Kristen Klein, Angela Whitaker-Williams	1/20/2021	
						•'				
1 - Exterior		1	2	3	4	5	N/A		8.75	69%
1.1 Does the pedestria	site permit desirable separation of vehicular, bus and un traffic?			3				Comments	1.00	3.00
1	Very unsatisfactory - Bus, car and pedestrian all happen at the same location									
2	Unsatisfactory - Cars and buses mix, pedestrians are separated									
3	Average - Buses, cars, and pedestrians are separate but stack space is small									
4	Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria									
5	Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination									
N/A	Does not apply									
1 1 2	lding easily identified with appropriate signage and ty wayfinding?				4			Comments	0.25	1.00
1	Very unsatisfactory - Campus has no signage /									
2	wayfinding Unsatisfactory - Signage/wayfinding is faded/hidden									
3	Average - Signage / wayfinding visible but not apparent									
4	Satisfactory - Signage / wayfinding is visible but not good condition									
5	Very satisfactory - Signage and wayfinding is visible and easy to use									
N/A	Does not apply									

02/11/2022 ²

1 - Exterior (co	ont.)	1	2	3	4	5	N/A			
1.3 Is the dum	pster accessible for trash / compost disposal?				4			Comments	0.50	2.00
1 2 3 4 5	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.									
N/A	Does not apply									
2 - Outdoor Le	earning and Activity	1	2	3	4	5	N/A	A.	10.00	80%
2.1 Are outdoon the ed spe	or studios and support spaces appropriately configured per c?			3				Comments	1.00	3.00
1 2 3 4 5 N/A	Very unsatisfactory - No dedicated outdoor studios Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area Does not apply									
22 Are active	playgrounds (elementary only) and support spaces d per the ed spec?						N/A	Comments	0.00	0.00
1 2 3 4 5 N/A	Very unsatisfactory - No dedicated active playground Unsatisfactory - Too small, poor condition, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure Satisfactory - Good size, good condition, more than 50% shade coverage over play structure Very satisfactory - Generous size, excellent condition, full shade coverage over play structure Does not apply									

2 - 0	Outdoor Le	arning and Activity (cont)	1	2	3	4	5	N/A	4		
2.3	-	s and support spaces appropriately configured per the ed		2					Comments		
2.0	spec? (eval	uation on infrastructure not condition of plants)		_					Comments	0.00	0.00
	1 2	Very unsatisfactory - No dedicated gardens Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source							Monitoring answer, does not affect score for Outdoor Activity.	Learning and	
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, water source is difficult to access									
	4	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, water source is accessible with 100 ft hose									
	5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation									
	N/A	Does not apply									
2.4	Are the rained spec?	n gardens and/or cisterns appropriately configured per the	1						Comments	0.00	0.00
	1 2 3	Very unsatisfactory - No rain gardens or cisterns Unsatisfactory - Too small, poor condition, not functioning, disconnected Average - Adequate size, adequate condition, is connected, needs some renovations or updates to function well							Monitoring answer, does not affect score for Outdoor Activity.	Learning and	
	4 5	Satisfactory - Good size, good condition, functions properly Very Satisfactory - Generous size, excellent condition,									
	N/A	exceptional functionality, connected to learning spaces, educational signage provided Does not apply									
2.5	Does the sc	hool have animal husbandry? (optional)	1						Comments	0.00	0.00
	1 5	No Yes	•	•							
2.6	Does the sc	hool have nature loop trails? (optional)	1						Comments	0.00	0.00
	1 5	No Yes									
2.7	Does the sc	hool have a learning pond? (optional)	1						Comments	0.00	0.00
	1 5	No Yes									
2.8	Does the sc	hool have a grass play field and walking trail?					5		Comments	1.00	5.00
	1	No							·		
	5	Yes									

3 - General Bu	ilding	1	2	3	4	5	N/A		11.25	36%
3 1	circulation routes wide enough to safely and effectively late student movement?				4			Comments	0.50	2.00
1 2 3 4 5 N/A	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0" wide Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide Average - Primary circulation is 7'-0" to 8'-0" wide Satisfactory - Primary circulation is 8'-0"-10'-0" wide Very satisfactory - Primary circulation is 10'-0"+ wide Does not apply					ı		The hallways range in size from 8 to 12 feet. This is problem principal notes: The hallways are jam packed, especially in any incident in the hallway it is very difficult to get around, need. The design of the school is such that all students are thallway, which is not big enough to handle. It is especially a weather days. We have to have a 6-minute passing period students cannot get to class on time.	atic for the scho center hall. If th or get to a stud funneled into or crowded on bac	ool. The nere is ent in ne main
3.2	inity use areas arranged so that the school can allow night rithout full school access?	1						Comments	0.75	0.75
1 2 3 4 5 N/A	Very unsatisfactory - Cafeteria, gym, and library cannot be accessed after hours Unsatisfactory - Only one of the public spaces (Cafeteria, Gym and Library) can be accessed from parking and secured after hours Average - Only two of the public spaces can be accessed from parking and secured after hours Satisfactory - All of the public spaces can be accessed from parking and secured from the rest of the building but not individually Very satisfactory - Cafeteria, gym, and library can be accessed from parking and locked off from rest of campus for night/evening use with their own entrance									
3 3 Is there a c	Does not apply ommunity room that is a dedicated meeting space outside	1						Comments		
of school fu 1 2 3 4 5	Very unsatisfactory - No dedicated community room Unsatisfactory - Community room but within school function, no access after school hours Average - Community room, moderate size, but need some renovations or updates to function well Satisfactory - Community room, good size /layout, meets needs /functions well Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function								0.75	0.75
N/A Does the g	Does not apply eneral appearance of the school convey pride for the							_		
3/1	nd community? Very unsatisfactory - General appearance is poor		2					Comments	0.25	0.50
1 2 3 4 5	Unsatisfactory - General appearance is poor Unsatisfactory - General appearance is aged but ok Average - General appearance is good Satisfactory - General appearance shows pride in campus and student works Very satisfactory - General appearance shows pride in campus and student works and is welcoming to the community Does not apply									

4 - Security		1	2	3	4	5	N/A		16.25	
4.1 Does the fo	acility have key card access at all major entries?							Comments	0.25	
1	Very unsatisfactory - No entries								•	
2	Unsatisfactory - 1/4 of major entries									
3	Average - 1/2 of major entries									
4	Satisfactory - 3/4 of major entries									
5	Very satisfactory - All of major entries									
N/A	Does not apply									
4.2 How adequ	uate is site lighting and security for the campus overall?							Comments	1.00	
1	Very unsatisfactory - No exterior lighting, no secure perimeter									
2	Unsatisfactory - Lighting is limited to front entry only, parking lot lighting poor, security is minimal									
3	Average - Lighting at all night-use entries and parking									
J	lot, but poor condition. Security is moderate									
4	Satisfactory - Lighting at all night-use entries and									
	parking lots, good condition, signage less visible,									
	perimeter is well secured but needs updates									
5	Very satisfactory - Signage, parking lots, and entries are									
	well lit, visible and easy to use, perimeter is very secure									
N/A	Does not apply	1	1						_	
	office located at the school entry and configured with a							Comments		
	tibule to the main corridor?		1			1			1.00	
1	Very unsatisfactory - No secure vestibule, office located far from main entry, allows visitors access to school									
	unsupervised									
2	Unsatisfactory - No secure vestibule, office located									
	somewhat far from main entry, minimal supervision of									
	visitors									
3	Average - Office close to entry, views of front door, but									
	no secure vestibule									
4	Satisfactory - Office is well-located with a secure									
	vestibule, but needs updates									
5	Very satisfactory - Office well-located with secure									
21/4	vestibule and all appropriate security features									
N/A	Does not apply							,		
1 /1 /1	ough interior transparency for faculty to passively supervise	1						Comments		
learners an	nd their activities who are not in studios?							35	1.00	1.00
1	Very unsatisfactory - No transparency of walls									
2	Unsatisfactory - Limited transparency in certain locations									
3	Average - Good transparency in certain locations but									
S	inadequate or missing in other locations of school									
4	Satisfactory - Adequate transparency throughout the									
	school									
5	Very satisfactory - Excellent transparency throughout the									
	school									
N/A	Does not apply									

Perkins&Will 02/11/2022 ⁶

	5 - Environmer	ntal Quality	1	2	3	4	5	N/A		25.00	48%
	5.1 How are ac	coustics in studios in general?		2					Comments	1.00	2.00
	1 2 3 4 5 N/A	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise from mechanical system Very satisfactory - Able to hear quiet speaking from across the room Does not apply									
	5.2 Is the studio	o artificial lighting adequate quality?			3				Comments	1.00	3.00
l l	1 2 3 4 5 N/A	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare Does not apply							Poor in older building, good in new building.		
	5.3 Is there acc	ess to natural light in studios?			3				Comments	1.00	3.00
	1 2 3 4 5	Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light							All studios on exterior walls have good natural light v	with blinds.	
ı	N/A	Does not apply		I	I					T	
		ess to outside views from learning spaces?			3				Comments	1.00	3.00
	1 2 3 4 5 N/A	Very unsatisfactory - No learning spaces have views Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out Average - 26-50% of learning spaces have views Satisfactory - 51-75% of learning spaces have views Very satisfactory - 76-100% of learning spaces have views Does not apply									

Perkins&Will 02/11/2022 ⁷

5 -	Environme	ntal Quality (cont.)	1	2	3	4	5	N/A	N.		
5.5	5 Does the b	uilding have odor or pest problems?	1						Comments	1.00	1.00
	1	Very unsatisfactory - Evidence of both pests and odors							Rats and raccoons. Major termite infestation.		
	2	Unsatisfactory - Evidence of pests or odors									
	3	Average - Limited evidence of pests, no odors									
	4	Satisfactory - No evidence of pests / odors, school									
		cleanliness in good condition									
	5	Very Satisfactory - No evidence, school cleanliness in									
		excellent condition									
	N/A	Does not apply									
6 -	Controllabi	lity of Systems	1	2	3	4	5	N/A		12.50	44%
6.	Does the st	udio thermostat allow for individual control?	1						Comments	0.50	0.50
	1	No							Thermostats present but do not function in many clas	ssrooms.	
	5	Yes									
6.2	2 Are shades	provided to control natural light in learning spaces?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No, windows are covered with							Principal's note - Most of the shades are in some sort	of disrepair. To	eachers
		boards/paper							resort to hanging up black sheets or butcher paper so	students can	see the
	2	Unsatisfactory - No, windows have no light control							screen.		
	3	Average - Yes, but poor condition blinds									
	4	Satisfactory - Yes, blinds									
	5	Very satisfactory - Blackout shades									
	N/A	Does not apply									
6.3	3 What is the	quality of lighting controls in the studios?		2					Comments	1.00	2.00
	1	Very unsatisfactory - Single switch only per room									
	2	Unsatisfactory - Alternating rows switch off									
	3	Average - Alternating lamps in single fixtures switch off									
	4	Satisfactory - Tri level switching									
	5	Very satisfactory - Dimmable									
	N/A	Does not apply									

7 - Furniture, f	Fixtures & Equipment	1	2	3	4	5	N/A		18.75	59%
7.1 What is the	e current condition of the furniture?				4			Comments	0.75	3.00
2	Very unsatisfactory - Damaged or broken, non- functioning Unsatisfactory - Torn/ bent/ wrong size									
3 4	Average - Scratched/dented/marked									
4 5	Satisfactory - Not new, but sturdy and clean									
N/A	Very satisfactory - New Does not apply									
14/4	воез пос арргу				I	1				
1 / ')	ety of furniture types being accommodated throughout the arning commons, dining commons, other multi-use spaces?		2					Comments	1.00	2.00
1	Very Unsatisfactory - Same furniture used in all spaces				•					
2	Unsatisfactory - Furniture variety in one multi-use space									
3	Average - Furniture variety in more than one multi-use space									
4	Satisfactory - All multi-use spaces have greater than one type of furniture									
5	Very satisfactory - All multi-use spaces have greater than									
	two types of furniture									
N/A	Does not apply does furniture accommodate rapid reconfiguration of a				ı	I	1	Т		
7.3 space?	aces turniture accommodate rapid reconfiguration of a			3				Comments	1.00	3.00
1	Very Unsatisfactory - Furniture is fixed or very heavy							'		
2	Unsatisfactory - Furniture does not allow desks to be configured as individuals, small groups, or large groups									
3	Average - Mix of furniture that can reconfigure but is									
4	cumbersome to move Satisfactory - Furniture is flexible for multiple									
·	configurations of space									
5	Very satisfactory - Furniture is flexible for multiple									
N/A	configurations of space, easy to move and stack									
	Does not apply									
7.4 Is the furni	ture ergonomic and size appropriate for grade level?			3				Comments	1.00	3.00
1	Very unsatisfactory - Desk with attached chair							Mixture of loose tables and charis and Chair desks combos	in older	
2	combinations too small for grade level Unsatisfactory - Desk with attached chair combinations							building.		
3	Average - Mix of studios with tables/loose chairs and									
3	desks with fixed seats									
4	Very satisfactory - Tables with loose chairs									
5	Very satisfactory - Tables with loose chairs that allow									
N/A	students to be active Does not apply									

Perkins&Will 02/11/2022 ⁹

Waste	1	2	3	4	5	N/A	5.00	809
Do studios and corridors have blue recycle bins with bilingual instructions and/or image sorting instructions?	1						Comments 0.50	0.9
1 Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins. 2 Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage. 3 Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage. 4 Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage. 5 Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus. N/A Does not apply	•						A score for this category is being recorded, but this category is not calculated in the overall ESA average.	
N/A Does not apply Does the cafeteria (or wherever meals are served) have at least one of each: green compost bin, blue recycle bin, and landfill bin? Are the bins labelled clearly with bilingual and/or image sorting?	Ī	2			5		Comments 0.50	3
 Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage. Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent. 							A score for this category is being recorded, but this category is not calculated in the overall ESA average.	
 Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent. Satisfactory- There are several waste stations as described above Very Satisfactory - There are several waste stations as described above, and additional signage in the cafeteria 								



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

Academics - Middle School / High School

School No	ame							Walk Attendees:	Date:	
McCallun	n HS					_		Kristen Klein, Angela Whitaker-Williams	1/20/2021	
						_				
8 - Academics	& Learning	1	2	3	4	5	N/A	A	65.00	43%
8.1 Are studio	s appropriately configured per the ed spec?		2					Comments	1.00	2.00
1 2 3 4	Very unsatisfactory - Too small, no flexibility, disconnected Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well. Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces									
N/A Do studios	Does not apply shave appropriate support spaces such as storage per the		1	1	l	1	1			
8.2 ed spec?	, mare appropriate support spaces such as stoluge per tile		2					Comments	1.00	2.00
1	Very unsatisfactory - None provided								- '	
2	Unsatisfactory - Too small, disconnected, poor condition									
3 4 5	Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition									
N/A	Does not apply									

Perkins&Will 02/11/2022 ²

8 - 1	Academics -	& Learning (cont.)	1	2	3	4	5	N/A			
8.3	Do typical l	earning neighborhoods have small and medium (high	1						Comments		
0.3	school only	group rooms and open collaboration space?	- 1						Comments	1.00	1.00
	1	Very unsatisfactory - No breakout rooms or open									
		collaboration spaces are provided									
	2	Unsatisfactory - Too small or too few, poor condition, no									
		flexibility, lacks visual connection to learning									
		neighborhood, poor acoustic privacy									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility,									
		transparency and connection to learning neighborhood,									
		acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition and									
		flexibility, transparency and connection to learning									
	_	neighborhood, acoustic privacy									
	N/A	Does not apply								T	
8.4		Labs and support spaces appropriately configured per		2					Comments		
	the ed spec			_					Commente	1.00	2.00
	1	Very unsatisfactory - No dedicated science room							Some labs recently renovated and have good suppo	rt (only 3 out o	f 11). The
	2	Unsatisfactory - Too small, poor condition, no connected							others are original, do not meet spec, and have no su	apport spaces.	
		support space									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
		support spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
	NI/A	connected support spaces									
	N/A	Does not apply		1		ı			Г	I	
8.5		Spaces and support spaces appropriately configured per	1						Comments		
	the ed spec	? (cross reference with CTE below)								1.00	1.00
	1	Very unsatisfactory - No dedicated maker spaces									
	2	Unsatisfactory - Too small, poor condition, disconnected									
		from learning spaces, no flexibility									
	3	Average - Adequate size, adequate condition, needs									
	_	some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected to									
	_	learning spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
	N1/A	connected to learning spaces									
	N/A	Does not apply									

Perkins&Will 02/11/2022 ³

8 - Academic	cs & Learning (cont.)	1	2	3	4	5	N/A			
8.6 Is there o	Professional Learning Center in the learning neighborhood?	1						Comments	1.00	1.00
1 2	Very unsatisfactory - No dedicated space for Professional Learning Center Unsatisfactory - Too small, poor condition, disconnected									
3 4	Average - Adequate size, adequate condition, needs some renovations or updates to function well Satisfactory - Good size, good condition, connected									
5	Very Satisfactory - Generous size, excellent condition, connected									
× /	e adequate places to display the evidence and artifacts of (both 2D and 3D)?			3				Comments	1.00	3.00
1 2	Very unsatisfactory - No dedicated space Unsatisfactory - Too small, non-dedicated, poor condition									
3	Average - Adequate size, adequate condition, needs updates or renovations to function well Satisfactory - Good size, good condition									
5 N/A	Very Satisfactory - Generous size, excellent condition Does not apply									
	building / learning neighborhood provide adequate nities for students/teachers to collaborate in varying group	1						Comments	1.00	1.00
1	Very unsatisfactory - No space to support collaboration in various sizes.									
2	Unsatisfactory - Too small, inflexible, only one option, does not support a variety of group sizes									
3	Average - Adequate space for collaboration, needs updates or renovations to function well. Satisfactory - Good size, good condition, multiple options									
5	to support a variety of group sizes Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes									
N/A	Does not apply									
	building provide opportunities for informal interaction?		2					Comments	1.00	2.00
1 2	Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well									
3 4	Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size, good condition, layout and									
5	furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions									
N/A	Does not apply									

O2/11/2022 ⁴

8 - <i>A</i>	3 - Academics & Learning (cont.)				3	4	5	N/A	1		
8.10	Does the building provide adequate opportunities for students to								Comments		
8.10	work indep	endently?	ı						Comments	1.00	1.00
	1	Very unsatisfactory - No breakout rooms/small study									
		spaces									
	2	Unsatisfactory - Too small, poor condition, no acoustic									
		privacy, only one space for independent work,									
		disconnected from learning neighborhood									
	3	Average - Adequate size and condition, needs updates									
		or renovations to function well.									
	4	Satisfactory - Good size and condition, acoustic privacy,									
		variety of independent work space options, connected to									
	-	learning neighborhood									
	5	Very Satisfactory - Generous size, excellent condition,									
		acoustic privacy, variety of independent work space									
	N/A	options, connected to learning neighborhood Does not apply									
	·										
	Special Edu			Γ	1		T		T		
8.11	-	Education spaces appropriately configured per the ed			3				Comments		
	spec?									1.00	3.00
	1	Very unsatisfactory - Too small, no flexibility,							Small resource rooms not adequate but life skills room	m well supporte	ed.
	2	disconnected									
	2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected									
	2	•									
	3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited									
		transparency and connection to other studios and									
		shared learning spaces, needs updates or renovations to									
		function well.									
	4	Satisfactory - Good size, multiple areas for different									
		teaching methods, good flexibility, good transparency									
		and connection to other studios and shared learning									
		spaces									
	5	Very Satisfactory - Generous size, multiple areas for									
		different teaching methods, excellent flexibility, generous									
		display area and visual teaching tools, excellent									
		transparency and connection with other studios and									
	N/A	shared learning spaces Does not apply									
	Are Special	Education support spaces, such as storage, space for									
8.12		rer, appropriately configured per the ed spec?				4			Comments	1.00	4.00
	1	Very unsatisfactory - None provided			1	1	1		Recently renovated		
	2	Unsatisfactory - Too small, disconnected, poor condition							lices in the second sec		
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply									

8 - Academics & Learning (cont.)	1	2	3	4	5	N/A			
8.13 Are Accessible restrooms and changing rooms readily available to the Special Education spaces?					5		Comments	1.00	5.00
1 No								1.00	3.00
5 Yes									
STEAM Center						Į.			
8.14 Does the campus have space to support a "STEAM" center?	1						Comments	0.00	0.00
1 Very unsatisfactory - No available space for STEAM center and inadequate studio / collaborative space 2 Unsatisfactory - Collaborative areas / studios for CTE/CCL are completely separate but adequate size 3 Neutral - Collaborative areas / studios for CTE/CCL are adjacent but function separately 4 Satisfactory - Collaborative areas / studios for CTE/CCL function and have space availability to create STEAM center 5 Very Satisfactory - Functioning STEAM center offers studios, labs, common collaborative areas to support multimedia distance and hands-on project based learning							Monitoring answer, but does not count toward overc	all score	
N/A Does not apply									
9 - CTE and Career Connected Learning								5.00	40%
9.1 How close is your campus to a CTE cluster pathway that is aligned with your CTE programs (Middle School only)?						N/A	Comments	0.00	0.00
1 Very unsatisfactory - No correlation to CTE cluster pathway, no CTE programs. 2 Unsatisfactory - School supports less than half of the CTE programs that are listed in the cluster pathway. 3 Average - School support half of CTE programs listed in the cluster pathway, but missing some. 4 Satisfactory - School support a majority of CTE programs listed in the CTE cluster pathway. 5 Very Satisfactory - School is aligned with CTE cluster pathway. N/A Does not apply									
9.2 Do campus facilities align with the CTE Ed Spec Requirements for the current pathways offered?: Architecture and Construction						N/A		0.00	0.00
1 No 5 Yes N/A Does not apply									
9.3 Arts, Audio and Video Technology and Communications	1							0.25	0.25
9.4 Business, Management and Administration					5			0.25	1.25
9.5 Education and Training						N/A		0.00	0.00
9.6 Health Science						N/A		0.00	0.00

9 - CTE and Career Connected Learning (cont.)	1	2	3	4	5	N/A			
9.7 Hospitality and Tourism						N/A		0.00	0.00
9.8 Human Services (high school only)						N/A		0.00	0.00
9.9 Information Technology						N/A		0.00	0.00
9.10 Agriculture, Food and Natural Resources						N/A		0.00	0.00
9.]] Science, Technology, Engineering, and Mathematics	1							0.25	0.25
9.12 Transportation, Distribution and Logistics						N/A		0.00	0.00
9.13 Finance (high school only)	1							0.25	0.25
9.14 Government and Public Administration / JROTC Military programs (high school only)						N/A			
(nigh school only)								0.00	0.00
9.15 Law, Public Safety, Corrections and Security (high school only)						N/A		0.00	0.00
9.16 Manufacturing (high school only)						N/A		0.00	0.00
9.17 Marketing, Sales and Services (high school only)						N/A		0.00	0.00
10 - Visual and Performing Arts								35.00	63%
10.1 Is there flexibility of space to also be used by CTE and Athletics?					5		Comments	0.00	0.00
1 No 5 Yes							Monitoring answer, but doesn't affect overall score.		
10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec?			3				Comments	1.00	3.00
Very unsatisfactory - Too small, missing program spaces									
2 Unsatisfactory - Too small, poor condition									
3 Neutral - Adequate size, adequate condition, needs									
updates or renovations to function well.									
4 Satisfactory - Good size, good condition									
5 Very Satisfactory - Generous size, excellent condition N/A Does not apply									
Are orchestra and support spaces appropriately configured per the			Π			<u> </u>			
10.3 ed spec?	1						Comments	1.00	1.00
Very unsatisfactory - Too small, missing program spaces							Space is much too small		
Unsatisfactory - Too small, poor condition									
· · · · · · · · · · · · · · · · · · ·									
3 Neutral - Adequate size, adequate condition, needs									
updates or renovations to function well.									
updates or renovations to function well. 4 Satisfactory - Good size, good condition									
updates or renovations to function well.									

10 - Visual and	10 - Visual and Performing Arts (cont.)					5	N/	/ A		
10.4 Are choir a spec?	nd support spaces appropriately configured per the ed				4			Comments	1.00	4.00
1	Very unsatisfactory - Too small, missing program spaces	•			•	•	•	30x40		
	U 0.6 v = U 100									
2	Unsatisfactory - Too small, poor condition									
3	Neutral - Adequate size, adequate condition, needs updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
ŭ	very successful serior successful containent									
N/A	Does not apply	ı		,		ı	-			
10.5	and support spaces appropriately configured per the ed			3	3			Comments		
spec?	V T								1.00	3.00
1	Very unsatisfactory - Too small, missing program spaces							Slated for new dance studio as part of the 2017 bond p	rogram. Nev	v desigr
2	Unsatisfactory - Too small, poor condition							needs to be evaluated.		
3	Neutral - Adequate size, adequate condition, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply	<u> </u>	T			1	ı			
10.6 spec?	r and support spaces appropriately configured per the ed					5		Comments	1.00	5.00
1	Very unsatisfactory - Too small, missing program spaces							Older theater seats 200. Recently redid rigging. Sound		
·	roly another action, recommending program opaciti							may need updating. Newer theater seats 500. Built 10	-	
2	Unsatisfactory - Too small, poor condition							school side meetings. Large theater has flooding issues	-	
3	Neutral - Adequate size, adequate condition, needs							Recent replacement of curtains.		
	updates or renovations to function well.							· ·		
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply									
Are visual	arts and support spaces appropriately configured per the					T		_		
10.7 ed spec?						5		Comments	1.00	5.00
1	Very unsatisfactory - Too small, missing program spaces					•				
2	Unsatisfactory - Too small, poor condition									
3	Neutral - Adequate size, adequate condition, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply									
	ampus have adequate space for the specialty arts	1						Comments		
programs (Ensemble, Guitar, Music studies, Music theory and Piano)?							25	1.00	1.00
1	No							In a portable		
5	Yes							· ·		

11 - Athletics and Wellness						26.25	58%
11.1 Does the campus meet ed spec standard for physical education program spaces?		2			Comments	1.00	2.00
Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition Average - Adequate size, adequate condition, needs some renovations or updates to function well Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition					Competition gym is very small (10,000 SF) compared t requirements, has too small audience space and no at practice gym. No exterior/public gym entry.	•	e in
N/A Does not apply 11.2 Does the campus have a dedicated wellness center?	1				Comments	0.50	0.50
1 No 5 Yes							
11.3 Does the community have access to exterior playfields/courts?				5	Comments	0.50	2.50
1 No 5 Yes							
17.4 Are facilities available to facilitate eSports (High School only)?	1				Comments	0.00	0.00
5 Yes	1				Monitoring answer, but doesn't affect overall score.		
1].5 Are facilities set up to support UIL sanctioned athletics for basketball? 1 No				5	Comments	0.25	1.25
1 No 5 Yes	1				Would like to reconfigure small gym to accommodate better scheduling of games	spectators ar	na allow
11.6 Are facilities set up to support UIL sanctioned athletics for track?	1				Comments	0.25	0.25
1 No 5 Yes					Facility supports practice, but does not support specta	tor events.	
11.7 Are facilities set up to support UIL sanctioned athletics for football?	1				Comments	0.25	0.25
1 No 5 Yes					Facility supports practice, but does not support specta natural turf.	tor events. Fig	eld is
17.8 Are facilities set up to support UIL sanctioned athletics for volleyball?				5	Comments	0.25	1.25
1 No 5 Yes							
11.9 Are facilities set up to support UIL sanctioned athletics for tennis?	1				Comments	0.25	0.25
1 No 5 Yes				1	Facility supports practice, but does not support specta	tor events.	
11.10 Are facilities set up to support UIL sanctioned athletics for soccer?	1				Comments	0.25	0.25
1 No 5 Yes					Facility supports practice, but does not support specta	tor events.	

Perkins&Will 02/11/2022 9

11 - Athletics and Wellness (cont.)	1	2	3	4	5	N/A			
Are facilities (dedicated storage) set up to support UIL sanctioned					E		Community		
athletics for cross-country (high school only)?					5		Comments	0.25	1.2
1 No		•		•			·		
5 Yes									
Are facilities (dedicated storage) set up to support UIL sanctioned					_		6		
athletics for golf (high school only)?					5		Comments	0.25	1.2
1 No							-		
5 Yes									
Are facilities (dedicated storage) set up to support UIL sanctioned									
athletics for swimming (high school only)?	1						Comments	0.25	0.2
1 No							Share facility at UT		
5 Yes							ondro racinty at or		
Are facilities set up to support IIII sanctioned athletics for wrestling									
(high school only)?					5		Comments	0.25	1.2
1 No								0.20	1,2
5 Yes									
Are facilities set up to support UIL sanctioned athletics for baseball							1		
11.15 (high school only)?					5		Comments	0.25	1.2
	<u> </u>						0 11 11 12	0.25	1.2
1 No 5 Yes							Small spectator seating		
- 1	1								
Are facilities set up to support UIL sanctioned athletics for softball					5		Comments	0.05	
(high school only)?	<u> </u>							0.25	1.2
1 No							Small spectator seating		
5 Yes									
Are facilities (dedicated space outside of the gymnasium) available to									
11.17 support competitive spirit activities for cheerleading and drill team?	1						Comments		
	<u> </u>							0.25	0.2
1 No									
5 Yes									
1 - Athletics and Wellness (cont.)	1	2	3	4	5	N/A			
How do the athletics fields align with FMP Campus Improvements?									
11.18 Turf Field, Parking lot lighting, ADA accessible amenities (high School	1						Comments		
only)								0.00	0.0
 Very unsatisfactory - No turf, inaccessible, no site lighting 							Monitoring answer, but doesn't affect overall score.		
							-		
2 Unsatisfactory - No turf/field in poor condition, some									
accessibility concerns, poor site lighting									
3 Average - Field in adequate condition, needs some									
updates or renovations to function well									
4 Satisfactory - Turf field in good condition, good ADA									
access and site lighting									
5 Very Satisfactory - Turf field with excellent maintenance,									
excellent ADA access for spectators and athletes,									
excellent site lighting									
N/A Does not apply.									

02/11/2022 ¹⁰

12 - Fo	od Servi	ces								10.00	50%
12.1 ls	the Dining	g Commons appropriately configured per the ed spec?			3				Comments	1.00	3.00
	1	Very unsatisfactory - Too small, missing program spaces									
	2	Unsatisfactory - Too small, poor condition, only one									
	2	option for eating space provided, inadequate circulation									
	3	Average - Adequate size and condition, needs updates									
	4	or renovations to function well Satisfactory - Good size and condition, good circulation,									
	4	multiple options for eating space (ex: connection to									
		outdoor eating space)									
	5	Very Satisfactory - Generous size, excellent condition and									
		circulation, multiple options for eating space (ex:									
		connection to outdoor eating space)									
	N/A	Does not apply									
Δ		d Services support spaces appropriately configured per				Т	Ι	Г			
1 12 2	ne ed spec	, , , , , , , , , , , , , , , ,		2					Comments	1.00	2.00
	1	Very unsatisfactory - None provided				-		1	Serving line too tight; manager desk located within k		
	2	Unsatisfactory - Too small, disconnected, poor condition								·	
	3	Neutral - Adequate size, average condition, needs									
	4	updates or renovations to function well									
	4 5	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent condition									
	N/A	Does not apply									
70 14				_	_	_	-			00.00	
	edia Res		ı	2	3	4	5	N/A		30.00	37%
133 1	the Librar isitors to th	y/Media Center easily accessible for the occupants and		2					Comments	1.00	2.00
V	1	Very unsatisfactory - Not accessible								1.00	2.00
	2	Unsatisfactory - Limited access, difficult to find, no									
	_	transparency									
	3	Average - Adequate accessibility, needs updates or									
		renovations to function well									
	4	Satisfactory - Accessible, easy to find, good									
		transparency, good condition									
	5	Very Satisfactory - Accessible, easy to find, excellent									
	N/A	transparency, excellent condition									

13 - Media Resources - Continued	1	2	3	4	5	N/A	A		
13.2 How well does the Library/Media Center support quiet study?							Comments	1.00	1.00
1 Very unsatisfactory - No quiet study spaces 2 Unsatisfactory - One area in poor condition, poor acoustic privacy 3 Average - One or more areas provided, needing updates or renovations to function well 4 Satisfactory - Clusters or small rooms adjacent to media center, good condition, good acoustic privacy 5 Very Satisfactory - Multiple clusters or small rooms adjacent to media center, excellent condition, excellent acoustic privacy N/A Does not apply									
13.3 How well does the Library/Media Center support social interaction?		2					Comments	1.00	2.00
Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size, good condition, layout and furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions N/A Does not apply									
13.4 How well does the Library/Media Center support collaborative work in small groups (4-8 students)?	1						Comments	1.00	1.00
1 Very unsatisfactory - No breakout rooms, no flexible furniture, no support 2 Unsatisfactory - Too small, one area, poor condition 3 Average - Adequate size, multiple areas provided, needing updates or renovations to function well 4 Satisfactory - Clusters or small rooms adjacent to media center, flexible furniture, good condition 5 Very Satisfactory - Multiple clusters or small rooms adjacent to media center, flexible furniture, excellent condition N/A Does not apply		I		I	1				
How well does the Library/Media Center support collaborative work in larger groups (10-25)?			3				Comments	1.00	3.00
1 Very unsatisfactory - No gathering areas 2 Unsatisfactory - Too small, one common space, limited seating, poor condition 3 Average - Adequate size, one common space, needs updates or renovations to function well 4 Satisfactory - Good size, multiple common spaces with seating, good condition 5 Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition									
N/A Does not apply									

Perkins&Will 02/11/2022 12

13 -	Media Res	ources - Continued	1	2	3	4	5	N/A	A		
13.6	How well d	oes the Library/Media Center support technology?		2					Comments	1.00	2.00
	1 2 3 4 5	Very unsatisfactory - No vis comm tools Unsatisfactory - Outdated, poorly functioning, or insufficient Average - Mix of old and new whiteboards/projectors/etc. Satisfactory - projectors, marker boards, smart boards in most spaces - good condition Very Satisfactory - projectors, marker boards, smart boards in most spaces - new condition				•					
14 -	N/A Technolog	Does not apply	1	2	3	4	5	N/A		20.00	45%
		quipped are the facilities with instructional technology?	•	2					Comments	1.00	2.00
	1 2 3 4 5 N/A	Very unsatisfactory - Limited to no technology present in instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards. Poor condition. Limited to only certain areas of school. Satisfactory - Multiple types of technology, smart boards. Good condition. Very Satisfactory - Multiple types of technology, smart boards. Excellent condition Does not apply									
14.2	Is there an spaces?	adequate number of power and data outlets in learning			3				Comments	1.00	3.00
	1 2 3	Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but limited capacity throughout school (3 per wall)							Original building lacking outlets; newer renovated sp	aces are well (covered.
	4 5	Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity in limited locations (>3 per wall) Very Satisfactory - Excellent outlet configuration to									
	N/A	support digital devices throughout school (>3 per wall) Does not apply									

Perkins&Will 02/11/2022 13

14 - Technology	y (cont.)	1	2	3	4	5	N/	/A
14.3 Are there a	dequate charging locations for devices?	1						Comments 1.00 1.
1 2 3 4 5	Very unsatisfactory - Not enough charging locations throughout school for 1:1 Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1 Satisfactory - Charging locations, haphazard locations, but supports 1:1. Very Satisfactory - Charging locations throughout school to support 1:1.							None observed
N/A	Does not apply							
14.4 Is there ade gym?	equate AV for presentations spaces – cafeteria, gym, aux			3				Comments 1.00 3.
1 2	Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room. Poor condition							
3	Average - AV adequately sized / poor condition OR AV undersized / average condition Satisfactory - AV adequately sized for room. Average							
5	Condition. Very Satisfactory - AV adequately sized for room. Excellent condition.							
N/A	Does not apply							
14.5 Is there digi	ital media signage at the reception area?	1						Comments 0.00 0 .
1 2 3 4 5	Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition OR undersized / adequate condition Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Generously sized, excellent condition							
N/A	Does not apply							1

15 - Administration Spaces	1	2	3	4	5	N/A	4	20.00	40%
15.1 Is there a reception area that functions as a security checkpoint for all visitors?							Comments	1.00	
1 Very unsatisfactory - No security checkpoint 2 Unsatisfactory - Checkpoint is too small, poor condition		•		-		•			
3 Average - Needs updates or renovations to function well									
4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply						_			
15.2 Does the administration area feel welcoming?			3				Comments	1.00	3.00
1 Very unsatisfactory - No welcome space 2 Unsatisfactory - Too small, poor lighting and transparency, limited informal seating, poor condition				1	•				
Average - Adequate size and layout, needs updates or renovations to feel welcoming Satisfactory - Good size and layout, good lighting and									
4 Satisfactory - Good size and layout, good lighting and transparency, informal seating provided									
5 Very Satisfactory - Generous size and layout, plenty of light and transparency, informal seating provided, excellent condition									
N/A Does not apply									
For those spaces that require it, does the administration area have adequate acoustic privacy?		2					Comments	1.00	2.00
Very unsatisfactory - No acoustic separations Unsatisfactory - Acoustic separations do not perform well									
3 Average - Some acoustic separations function okay, but portions need updates or renovations									
4 Satisfactory - Good acoustic separations									
5 Very Satisfactory - Excellent acoustic separations N/A Does not apply									
15.4 Are conference rooms easily accessed for public / parent use?		2					Comments	1.00	2.00
1 Very unsatisfactory - Not accessible for public/parent use		•				•			
2 Unsatisfactory - Limited access, no transparency, poor condition, difficult to find									
Average - Adequate accessibility, needs updates or renovations to function well									
4 Satisfactory - Good accessibility, good transparency, good size and condition									
5 Very Satisfactory - Excellent accessibility, excellent transparency, generous size, excellent condition									
N/A Does not apply							L.		